



Robbins Road overview mapping



Upstream side of culvert (note: invert of culvert is gone)



Stone placed in the voids to slow failure.



Pipe pulling away from the surrounding soil.