



Longitudinal cracking and undermined guard rail along edge - Work Area A



Eroding slopes over box culvert – Work Area B