## **CODE DEFICIENCIES - EXHIBIT A**

CASE NO: 2014090386 NEIGHBORHOOD CONSERVATION OFFICER: DARYL GREEN - (336)734-1276

1171 SALEM LAKE RD

## VIOL NBR VIOLATION DESCRIPTION STATUS/ORDINANCE

811273 REPLACE BROKEN WINDOW PANES - COMPLIED V-10-197(B)(4)

811642 10-MONTH WARRANTY INSPECTION - BACK DOOR BROKEN/BUSTED OUT, ALLOWING ACCESS TO HOUSE.

**COMPLIED** 

811639 PAINT OR TREAT EXTERIOR WOOD WITH PROTECTIVE COATING - MINOR V-10-197(G)(3)

811640 REPAIR OR REPLACE DEFECTIVE SIDING - Deteriorated siding at the base of the fireplace chase. Hole in siding on the north side.

MINOR V-10-197(G)(3)

811644 REPAIR HOLES IN WALLS AND CEILINGS - nwBRw. MINOR V-10-197(G)(4)

811632 REPAIR DOOR - 1. Patio door, back entrance, glass broken. 2. nwBR door with hole and broken lockset area.

UNFIT V-10-197(A)(15)

811633 REPAIR LOCKSETS - nwBR door missing lockset, privacy UNFIT V-10-197(B)(4)

811634 REPAIR OR REPLACE SCREENS ON DOORS - back entrance screen damaged UNFIT V-10-197(B)(3)

811635 REPAIR OR REPLACE SCREENS ON WINDOWS - 2 back windows missing screens. UNFIT V-10-197(B)(3)

811636 Heating facilities, central or other, shall be properly installed and maintained. 10-197(e)(2) - nwBRw. Thermostat missing control knob.

UNFIT V-10-197

811637 All fixtures shall be properly maintained in a safe, sanitary, and functional condition. 10-197(d)(2) - Toilets

UNFIT V-10-197

811638 REPAIR DEFECTIVE FLOORING - Hole in floor in utility area off of the hall. UNFIT V-10-197(G)(2)

811641 PROVIDE OPERABLE SMOKE DETECTOR - Smoke detectors required in the hall and in each of the 3 bedrooms.

UNFIT V-10-197(L)(1)