




West Lakeview Drive Bridge



Overtopping during storm events



Corrosion of support beams



Concrete damage to railing and abutment structures