## **CODE ENFORCEMENT PURSUANT TO SEC. 10-203(e) OF THE HOUSING CODE**

1726 WAUGHTOWN ST

CASE SUMMARY - HOUSING FILE NO. 2013040767

PROPERTY ADDRESS

the value.

	TAX BLOCK <u>1738</u> LOT(s) <u>105</u>
	WARD <u>SOUTHEAST</u>
	PROPERTY OWNER(s) MARK A. & REBECCA R. UNDERWOOD
	LIS PENDENS <u>13m1581</u> FILED <u>7/3/2013</u>
<u>DUE PROCESS</u>	
1.	The initial housing inspection was conducted on <u>4/11/2013</u> as a result of <u>MINOR</u> .
2.	The current <u>Complaint and Notice of Hearing</u> was issued <u>4/23/2013</u> and service was obtained by certified mail <u>x</u> regular <u>x</u> post <u>x</u> hand delivery, and publication on <u>4/26/2013</u> . The Hearing was held on <u>5/23/2013</u> and the owner/agent appeared and/or contacted the Community and Business Development Department regarding the complaint. yes no <u>x</u> .
3.	The <u>Finding and Order</u> was issued on <u>6/5/2013</u> and service was obtained by certified mail <u>x</u> regular <u>x</u> post <u>x</u> hand delivery and publication on <u>6/6/2013</u> . The <u>Order</u> directed the owner to <u>vacate and close or repair</u> the dwelling within <u>30</u> days from receipt. Time for compliance expired on <u>7/6/2013</u> .
4.	The notification letter was sent <u>10/24/2013</u> advising the owner that the Community Development/Housing/General Government Committee of the City Council would be considering demolition of this dwelling at their meeting on <u>11/19/2013</u> . The notice further advised that if they intended to request an extension of time, they should present evidence of their intent to the Community and Business Development Director prior to the Committee meeting. Director was contacted yes <u>no x</u> .
COMMENTS (if any)	
COUNCIL CONSIDERATION	
The estimated cost to make repairs to bring this substandard structure into compliance with Housing Code Standards as prescribed in the Housing code exceeds sixty-five percent (65%) of	

Based on the above information, it is recommended that an Ordinance be adopted to cause this dwelling to be **removed or demolished.** 

Estimated cost to repair \$173,920 Fair market value \$48,848