



Neighborhood Services
Department

City of Winston-Salem
P.O. Box 2511
Winston-Salem, NC 27102
336-722-8000
CityofWS.org

CODE ENFORCEMENT PURSUANT TO HOUSING CODE: ☐ SEC. 10-203(e)
☐ SEC. 10-203(f)(1)
☒ SEC. 10-203(f)(2)

CASE SUMMARY:

HOUSING FILE NO.: CE-H-VIO-24-08-0033

PROPERTY ADDRESS: 1135 ARGONNE BV

WARD: Southeast 1

PROPERTY OWNER(s): JACOB L. JOHNSON

LIS PENDENS #: 24M1509 DATE LIS PENDENS FILED: 11/19/2024

DUE PROCESS:

1. The current **Complaint and Notice of Hearing** was issued **10/29/2024** and service was obtained by ☒ certified mail; ☒ regular; ☒ posting; ☒ hand delivery and ☐ publication on **11/4/2024**. The Hearing was held on **11/28/2024** and the owner/agent ☐ did ☒ did not appear and/or contact the Community Development Department regarding the complaint.
2. The **Finding and Order** was issued on **01/17/2025** and service was obtained by ☒ certified; ☒ regular; ☒ posting; ☐ hand delivery, and ☐ publication on **1/21/2025**. The Order directed the owner to **repair, alter or improve** the dwelling within **30** days from receipt. The time for compliance expired on **2/17/2025**. The dwelling was found vacated and closed on **2/20/2025**.
3. The dwelling became eligible for demolition under the ☒ six (6) month rule ☐ 65% rule on **8/27/2025**.
4. The notification letter was sent on **2/18/2025** advising the owner that the **General Government Committee** of the City Council would be considering demolition of this dwelling at their meeting on **3/9/2024**. The notice further advised that if the owner(s) intended to request an extension of time, they should present evidence of their intent to the Neighborhood Services Director prior to the Committee meeting. The Director ☐ was ☒ was not contacted.

COMMENTS (if any):

COUNCIL CONSIDERATION:

The estimated cost to make repairs to needed to render this dwelling fit for human habitation:

- ☐ exceeds sixty-five percent (65%) of the value of the dwelling.
☐ is less than fifty percent (<50%) of the present value of the dwelling.
☒ is more than fifty percent (>50%) of the present value of the dwelling.

Estimated cost to repair structure \$11,846

Tax value of structure \$12,500

Based on the above information it is recommended that an Ordinance be adopted to cause this dwelling to be:

- ☐ removed or demolished.
☐ repaired or demolished and removed within ninety (90) days
☒ demolished and removed within ninety (90) days.