CODE DEFICIENCIES - EXHIBIT A

CASE NO: 2016020393 NEIGHBORHOOD CONSERVATION OFFICER: KELLY SPEAKS - (336)734-1273

643 KAPP ST

VIOL NBR VIOLATION DESCRIPTION STATUS/ORDINANCE

845912 REPAIR FURNACE - HEAT NOT WORKING COMPLIED V-10-197(E)(2)

845916 OTHER - REPAAIR SUMP PUMP COMPLIED V-10-197

845918 PROVIDE ADEQUATE SERVICE EQUIPMENT AND LIGHTING PANEL - COMPLIED V-10-197(F)(10)

845907 WEATHERSTRIP DOORS - MINOR V-10-197(B)(4)

845911 REPAIR DEFECTIVE SWITCHES AND/OR OUTLETS TO INCLUDE COVERS - MINOR V-10-197(F)(1)

845913 REPAIR KITCHEN CABINETS - MINOR V-10-197(A)(16)

845906 PROVIDE DOOR - INTERIOR DOOR AT FRONT ENTRANCE UNFIT V-10-197(A)(15)

845908 REPLACE BROKEN WINDOW PANES - UNFIT V-10-197(B)(4)

845909 REPAIR WINDOW LOCKS - UNFIT V-10-197(B)(4)

845919 REPAIR SEWER LINE - SINKS BACKED UP TERRIBLY UNFIT V-10-197(D)(15)

845920 PROVIDE PROPER DISCHARGE TUBE - HOT WATER HEATER - UNFIT V-10-193(7)

845910 OTHER - WINDOWS SHOULD BE OPEARABLE UNFIT HAZARDOUS V-10-197

845914 REPAIR PLUMBING LEAK UNDER STRUCTURE - UNFIT HAZARDOUS V-10-197(D)(15)

845917 REPAIR FURNACE - REPLACE UNCOVERD EXPOSED WIRE UNFIT HAZARDOUS V-10-197(E)(2)

 $845921\,$ REPAIR DEFECTIVE SWITCHES AND/OR OUTLETS TO INCLUDE COVERS $\,$ - OUTLET UNCOVERED

UNFIT HAZARDOUS V-10-197(F)(1)