



CODE DEFICIENCIES - EXHIBIT A

CASE NO: 2022080942

NEIGH. CONSERVATION OFFICER:

TONY WRIGHT - (336)734-1267

LOCATION: 1508 E TWENTY-SECOND ST

<u>VIOL NBR</u>	<u>VIOLATION DESCRIPTION</u>	<u>STATUS/ORDINANCE</u>
------------------------	-------------------------------------	--------------------------------

965887	PAINT OR TREAT EXTERIOR WOOD WITH PROTECTIVE COATING - REAR	
--------	---	--

MINOR V-10-197(G)(3)

965880	REPAIR SOFFIT AND/OR FASCIA - FRONT	
--------	-------------------------------------	--

UNFIT V-10-197(G)(6)

965882	REPAIR PORCH COLUMNS - BACK PORCH	
--------	-----------------------------------	--

UNFIT V-10-197(G)(7)

965883	REPAIR OR REPLACE FRONT PORCH CEILING -	
--------	---	--

UNFIT V-10-197(G)(7)

965884	REPAIR OR REPLACE ROOF COVERING - REAR PORCH AREA	
--------	---	--

UNFIT V-10-197(G)(6)

965885	REPAIR OR REPLACE REAR PORCH FLOOR -	
--------	--------------------------------------	--

UNFIT V-10-197(G)(7)

965886	REPAIR OR REPLACE REAR PORCH RAILINGS - BACK STEPS	
--------	--	--

UNFIT V-10-197(G)(7)

965888	REPAIR FOUNDATION VENTS - 3 (RIGHT SIDE AND BACK)	
--------	---	--

UNFIT V-10-197(h)(6)(b)

965889	REPAIR CRAWL SPACE DOOR - REAR	
--------	--------------------------------	--

UNFIT V-10-197(G)(1)

965890	REPAIR DOOR - REAR STORM DOOR	
--------	-------------------------------	--

UNFIT V-10-197(A)(15)