

## Community Development Department

City of Winston-Salem PO. Box 2511 Winston-Salem, NC 27102 CityLink 311 (336-727.8000) Fax 336-727.2878 www.cityofur.org

## **CODE DEFICIENCIES - EXHIBIT A**

CASE NO: 2022050753

NEIGH. CONSERVATION OFFICER: TONY WRIGHT - (336)734-1267

**LOCATION: 1427 E TWENTY-THIRD ST** 

VIOL NBR VIOLATION DESCRIPTION STATUS/ORDINANCE

961386 THE REPAIR OF THE STRUCTURE WILL EXCEED SIXTY-FIVE PERCENT (65%) OF THE VALUE -

DEMO V-97-(B)(2)

961361 CARBON MONOXIDE DETECTOR, OPERABLE, REQUIRED ON EACH LEVEL OF THE STRUCTURE. APPLIES TO UNITS WITH FOSSIL FUEL FURNING APPLIANCES/FIREPLACES AND ANY UNIT WITH AN ATTACHED GARAGE. THE DETECTOR MAY BE BATTERY POWERED OR HARD-WIRED. - UNFIT Sec. 10-197(m1)

961362 PAINT WALLS AND CEILINGS - UNFIT V-10-197(G)(4)

961363 PROVIDE ADEQUATE SERVICE EQUIPMENT AND LIGHTING PANEL - UNFIT V-10-197(F)(10)

961364 PROVIDE JUNCTION BOXES - UNFIT V-10-197(F)(5)

961365 PROVIDE OPERABLE SMOKE DETECTOR - UNFIT V-10-197(L)(1)

961366 REMOVE AND REPLACE FIRE DAMAGED PORTION OF STRUCTURE - UNFIT V-4-89(4)

961367 REPAIR DEFECTIVE FLOORING - UNFIT V-10-197(G)(2)

961368 REPAIR DEFECTIVE LIGHT FIXTURES - UNFIT V-10-197(F)(1)

961369 REPAIR DEFECTIVE SWITCHES AND/OR OUTLETS TO INCLUDE COVERS - UNFIT V-10-197(F)(1)

961370 REPAIR DOOR - UNFIT V-10-197(A)(15)

961371 REPAIR HOLES IN WALLS AND CEILINGS - UNFIT V-10-197(G)(4)

961372 REPAIR OR REPLACE DEFECTIVE SIDING - UNFIT V-10-197(G)(3)

961373 REPAIR OR REPLACE ROOF COVERING

- UNFIT V-10-197(G)(6)
- 961374 REPAIR OR REPLACE SCREENS ON DOORS UNFIT V-10-197(B)(3)
- 961375 REPAIR OR REPLACE SCREENS ON WINDOWS UNFIT V-10-197(B)(3)
- 961376 REPAIR PLUMBING LEAK IN BATH UNFIT V-10-197(D)(15)
- 961377 REPAIR PLUMBING LEAK IN KITCHEN UNFIT V-10-197(D)(15)
- 961378 REPAIR PLUMBING LEAK UNDER STRUCTURE UNFIT V-10-197(D)(15)
- 961379 REPAIR ROOF LEAK -UNFIT V-10-197(G)(6)
- 961380 REPAIR SOFFIT AND/OR FASCIA UNFIT V-10-197(G)(6)
- 961381 REPLACE BROKEN WINDOW PANES UNFIT V-10-197(B)(4)
- 961382 REPLACE DEFECTIVE JOISTS UNFIT V-10-197(G)(2)
- 961383 REPLACE DEFECTIVE RAFTERS UNFIT V-10-197(G)(6)
- 961384 REPLACE DEFECTIVE SHEATHING UNFIT V-10-197(G)(6)
- 961385 REPLACE LOOSE WALL AND CEILING MATERIALS UNFIT V-10-197(G)(4)
- 961387 WEATHERSTRIP DOORS -UNFIT V-10-197(B)(4)