

Community Development Department

City of Winston-Salem PO. Box 2511 Winston-Salem, NC 27102 CityLink 311 (336-727.8000) Fax 336.727.2878 www.cityofus.org

CODE DEFICIENCIES - EXHIBIT A

CASE NO: 2021020642

NEIGH. CONSERVATION OFFICER: MATTHEW WARREN - (366)734-1287

LOCATION: 1621 ROCKFORD ST

VIOL NBR VIOLATION DESCRIPTION STATUS/ORDINANCE

963157 THE REPAIR OF THE STRUCTURE WILL EXCEED SIXTY-FIVE PERCENT (65%) OF THE VALUE - DEMO V-97-(B)(2)

945219 REPAIR OR REPLACE FRONT PORCH CEILING - MINORV-10-197(G)(7)

945212 PROVIDE R-19 CEILING INSULATION - REAR MINORV-10-197(I)

945215 PROVIDE SAFE STEPS TO SERVE EXITS - REAR UNFIT V-10-197(C)(2)

945216 OTHER - REMOVE TREE FROM HOUSE UNFIT V-10-197

945217 REPAIR DEFECTIVE FLOORING - REAR UNFIT V-10-197(G)(2)

945220 REPAIR SOFFIT AND/OR FASCIA - WHERE NEEDED UNFIT V-10-197(G)(6)

945221 REPAIR, REPLACE OR REMOVE GUTTERS AND DOWNSPOUTS - UNFIT V-10-197(G)(6)

945222 REPLACE BROKEN WINDOW PANES - REAR UNFIT V-10-197(B)(4)

945211 EXTERIOR AND INTERIOR FRAMING MUST BE INSPECTED BEFORE COVERING WITH WALL AND CEILING MATERIALS - UNFIT V-4-91

945223 REPLACE DEFECTIVE SHEATHING - UNFIT V-10-197(G)(6)

945213 PROVIDE SAFE HANDRAILS TO SERVE EXITS - BACK UNFIT V-10-197(C)(2)

945214 PROVIDE SAFE PLATFORMS TO SERVE EXIT - UNFIT V-10-197(C)(2)

945209 REPAIR OR REPLACE ROOF COVERING - UNFIT V-10-197(G)(6)