CODE ENFORCEMENT PURSUANT TO SEC. 10-203(f)(1) OF THE HOUSING CODE

CASE	SUMMARY -			<u>2012051</u>		
	PROPERTY A		<u> 2017 E EIG</u>		H ST	
	TAX BLOCK		LOT(s)	<u>066</u>		
		NORTHEAS				
	PROPERTY	` '				RY W MICKEY
	LIS PENDEN	S <u>12M</u>	[2331FIL	ED <u>08/29</u>	9/2012	
<u>DUE</u>]	PROCESS					
1.	The current Co service was ob publication and the owner/ Department reg	otained by cert on <u>06/26/</u> agent appeare	tified mail \underline{x} reconstruction \underline{x} in \underline{x} . The left and/or contains	egular <u>x</u> po Hearing wa acted the C	st <u>x</u> hand de s held on <u>07</u> ommunity D	livery, and 7/23/2012
2.		tified <u>x</u> regul . The Order of within <u>30</u> days	ar \underline{x} post \underline{x} handirected the own from receipt.	d delivery_ ner to <u>vac</u> Time for c	, and pu ate and clos ompliance e	blication on e or repair
3.	The dwelling b _06/13/2013		e for demolition	on under the	e six (6) mon	nth rule on
4.	Council would 04/11/2017	evelopment/ I be considering. The notice me, they show Director prior	Housing/General Memory	eral Gover of this dwe d that if the dence of the	nment Come elling at their ey intended their intent to	amittee of the City r meeting on to request an the Community
COM	MENTS (if any)				
COUN	NCIL CONSID	<u>ERATION</u>				
	stimated cost to a tion is less than					

Estimated cost to repair \$977.00 Fair market value \$10,017.00 Based on the above information it is recommended that an Ordinance be adopted to cause this dwelling to be repaired or demolished and removed within ninety (90) days. This structure can be repaired under In Rem provisions of the Minimum Housing Code with City Council approval.