CODE DEFICIENCIES - EXHIBIT A

CASE NO: 2010041840 NEIGHBORHOOD CONSERVATION OFFICER: CHRISTOPHER RUSSELL - (336)734-1269

2912 WEISNER CT

VIOL NBR VIOLATION DESCRIPTION STATUS/ORDINANCE

674459 REPAIR SOFFIT AND/OR FACIA - IN REAR UNFIT V-10-197(G)(6)

674461 REPAIR, REPLACE OR REMOVE GUTTERS AND DOWNSPOUTS - IN REAR UNFIT V-10-197(G)(6)

674463 REPAIR CHIMNEY - REPAIR MOULDING AROUND CHIMNEY UNFIT V-10-197(E)(5)

850311 PAINT OR TREAT EXTERIOR WOOD WITH PROTECTIVE COATING - SEC. 10-197(G)(3)(H) ALL EXTERIOR SURFACES, OTHER THAN DECAY RESISTANT MATERIALS, SHALL BE PROTECTED FROM THE ELEMENTS AND DECAY BY PAINTING OR OTHER PROTECTIVE COVERING OR TREATMENT. UNFIT V-10-197(G)(3)

850302 OTHER - SEC. 10-197(G)(2)(A) NO ROTTED OR TERMITE-DAMAGED SILLS SHALL BE ALLOWED.

UNFIT V-10-197

850303 OTHER - SEC.10-197(G)(2)(F) NO ROTTED, SERIOUSLY FIRE DAMAGED, OR TERMITE-DAMAGED JOISTS SHALL BE ALLOWED.

UNFIT V-10-197

850228 REPAIR OR REPLACE DEFECTIVE SIDING - SEC. 10-197(G)(3)(C) NO STUDS WHICH ARE ROTTED, SERIOUSLY FIRE DAMAGED, OR TERMITE-DAMAGED SHALL BE ALLOWED.; SEC.10-197(G)(3)(F) ALL SIDING SHALL BE WEATHERTIGHT, WITH NO HOLES, CRACKS OR ROTTED BOARDS WHICH PERMIT AIR EXCESSIVELY TO PENETRATE ROOMS. UNFIT V-10-197(G)(3)

850229 REPAIR OR REPLACE REAR PORCH FLOOR - REAR DECK UNFIT V-10-197(G)(7)

850230 REPAIR OR REPLACE REAR PORCH RAILINGS - REAR DECK UNFIT V-10-197(G)(7)

850231 REPAIR PORCH COLUMNS - REAR DECK UNFIT V-10-197(G)(7)

850232 REPAIR PORCH COLUMNS - REAR DECK UNFIT V-10-197(G)(7)

 $850233\,$ HAVE STRUCTURE EXTERMINATED OF INSECTS, RODENTS - OTHER PESTS $\,$ - TO INCLUDE TERMITES

UNFIT V-10-197

850234 PROVIDE SAFE PLATFORMS TO SERVE EXIT - REAR UNFIT V-10-197(C)(2)