

Community Development Department

City of Winston-Salem PO. Box 2511 Winston-Salem, NC 27102 CityLink 311 (336-727.8000) Fax 336-727.2878 www.cityofur.org

CODE DEFICIENCIES - EXHIBIT A

CASE NO: 2019120305

NEIGH. CONSERVATION OFFICER: MARCO RAMOS - (336)734-1269

LOCATION: 5311 SILAS CREEK PW

VIOL NBR VIOLATION DESCRIPTION STATUS/ORDINANCE

930975 THE REPAIR OF THE STRUCTURE WILL EXCEED SIXTY-FIVE PERCENT (65%) OF THE VALUE - DEMO V-97-(B)(2)

930969 PROVIDE R-19 CEILING INSULATION - MINORV-10-197(I)

930977 REPAIR SOFFIT AND/OR FASCIA UNFIT V-10-197(G)(6)

930956 REPLACE BROKEN WINDOW PANES - UNFIT V-10-197(B)(4)

930957 REPLACE LOOSE WALL AND CEILING MATERIALS - UNFIT V-10-197(G)(4)

930958 REPAIR OR REPLACE ROOF COVERING UNFIT V-10-197(G)(6)

930959 REPAIR OR REPLACE SCREENS ON DOORS - UNFIT V-10-197(B)(3)

930960 REPAIR OR REPLACE DEFECTIVE SIDING - UNFIT V-10-197(G)(3)

930961 REPAIR KITCHEN CABINETS - UNFIT V-10-197(A)(16)

930962 REPAIR LAVATORY AND/OR FIXTURES - UNFIT V-10-197(D)(10)

930963 REPAIR KITCHEN SINK, FIXTURES AND/OR DRAIN - UNFIT V-10-197(D)(10)

930964 REPAIR KITCHEN CABINETS - UNFIT V-10-197(A)(16)

930965 REPAIR HOLES IN WALLS AND CEILINGS - UNFIT V-10-197(G)(4)

930966 REPAIR FURNACE UNFIT V-10-197(E)(2)

930967 REPAIR DEFECTIVE LIGHT FIXTURES -

UNFIT V-10-197(F)(1)

- 930968 REMOVE AND REPLACE FIRE DAMAGED PORTION OF STRUCTURE UNFIT V-4-89(4)
- 930970 PROVIDE OPERABLE SMOKE DETECTOR UNFIT V-10-197(L)(1)
- 930971 PROVIDE ADEQUATE SERVICE EQUIPMENT AND LIGHTING PANEL UNFIT V-10-197(F)(10)
- 930972 EXTERIOR AND INTERIOR FRAMING MUST BE INSPECTED BEFORE COVERING WITH WALL AND CEILING MATERIALS UNFIT V-4-91
- 930973 CARBON MONOXIDE DETECTOR, OPERABLE, REQUIRED ON EACH LEVEL OF THE STRUCTURE. APPLIES TO UNITS WITH FOSSIL FUEL FURNING APPLIANCES/FIREPLACES AND ANY UNIT WITH AN ATTACHED GARAGE. THE DETECTOR MAY BE BATTERY POWERED OR HARD-WIRED. UNFIT SEC. 10-197(M1)
- 930974 PROVIDE PROPER DISCHARGE TUBE HOT WATER HEATER UNFIT V-10-193(7)
- 930976 PROTECT WATER PIPING FROM FREEZING UNFIT V-10-197(D)(13)