

REPLACEMENT INFORMATION			
Vehicle #	438	456	464
Year	2004	2004	2004
Make/Model	Sterling	Sterling	Sterling
Mileage	97043	105144	112584
Acquired Cost	\$125,455.33	\$125,455.33	\$125,455.33
Repair Cost	\$165,059.05	\$191,949.59	\$145,194.85

WORKFORCE DEMOGRAPHICS								
Project/Bid Description:	<u>Rear Loading Refuse Trucks</u>							
Bidder's Company Name:	<u>Carolina Environmental Systems, Inc</u>							
City/State:	<u>Greensboro, NC</u>							
	<u>Gender</u>		<u>Race/Ethnic Identification</u>					
	<u>Male</u>	<u>Female</u>	<u>White</u>	<u>African-</u>	<u>Hispanic</u>	<u>Asian</u>	<u>Native-</u>	<u>Total</u>
	<u>58</u>	<u>7</u>	<u>58</u>	<u>American</u>	<u>3</u>	<u>0</u>	<u>American</u>	<u>65</u>
% of								
Total	89.2%	10.8%	89.2%	6.2%	4.6%	0.0%	0.0%	
<p>The above demographic data is provided to reflect generally the company's efforts to achieve diversity in the workplace in compliance with the applicable equal employment opportunity laws; however, this information is not dispositive of such and may not be used as the basis for awarding or rejecting a bid contract.</p>								