



CODE DEFICIENCIES - EXHIBIT A

CASE NO: 2020060294

NEIGH. CONSERVATION OFFICER: SHAWN HELM - (336)734-1271

LOCATION: 3873 BARKWOOD DR

**VIOL NBR VIOLATION DESCRIPTION
STATUS/ORDINANCE**

934729 REPAIR FOUNDATION VENTS - FRONT OF STRUCTURE
MINORV-10-197(H)(6)(B)

934734 REPAIR OR REPLACE SCREENS ON WINDOWS -
MINORV-10-197(B)(3)

934735 REPAIR OR REPLACE ROOF COVERING -
UNFIT V-10-197(G)(6)

934727 PROVIDE DOOR - FRONT DOOR, SIDE DOOR ON DRIVEWAY SIDE.
UNFIT V-10-197(A)(15)

934731 REPAIR SOFFIT AND/OR FASCIA -
UNFIT V-10-197(G)(6)

934732 REPAIR THRESHOLD -
UNFIT V-10-197(B)(4)

934733 REPLACE BROKEN WINDOW PANES - WINDOWS IN BACK OF STRUCTURE.
UNFIT V-10-197(B)(4)

934728 REMOVE AND REPLACE FIRE DAMAGED PORTION OF STRUCTURE -
UNFIT V-4-89(4)

Community Development
Department

City of Winston-Salem
P.O. Box 2511
Winston-Salem, NC 27102
CityLink 311 (336.727.8000)
Fax 336.727.2878
www.cityofws.org