

Exhibit B



Sinkhole at the sidewalk



Damaged waterline from failing culvert wall



Exhibit B



Undermined headwall



Remains of wooden piers in the floor of the culvert