

PIN: 6846-02-4917.000

Violation Type: Housing Violation

Block: 1382

Lot: 001

Location: 1511 ATTUCKS ST 0, WS, , 27105

File name (Image): REAR-FOUNDATION.jpg



PIN: 6846-02-4917.000

Violation Type: Housing Violation

Block: 1382

Lot: 001

Location: 1511 ATTUCKS ST 0, WS, , 27105

File name (Image): FOUNDATION-RIGHT-SIDE.jpg



PIN: 6846-02-4917.000

Violation Type: Housing Violation

Block: 1382

Lot: 001

Location: 1511 ATTUCKS ST 0, WS, , 27105

File name (Image): BROKEN-SCREENS-AND-WINDOWS.jpg



PIN: 6846-02-4917.000

Violation Type: Housing Violation

Block: 1382

Lot: 001

Location: 1511 ATTUCKS ST 0, WS, , 27105

File name (Image): BROKEN-WINDOWS.jpg



PIN: 6846-02-4917.000

Violation Type: Housing Violation

Block: 1382

Lot: 001

Location: 1511 ATTUCKS ST 0, WS, , 27105

File name (Image): LEFT-SIDE-EXTERIOR.jpg



PIN: 6846-02-4917.000

Violation Type: Housing Violation

Block: 1382

Lot: 001

Location: 1511 ATTUCKS ST 0, WS, , 27105

File name (Image): BROKEN-WINDOWS-AND-SCREENS.jpg



PIN: 6846-02-4917.000

Violation Type: Housing Violation

Block: 1382

Lot: 001

Location: 1511 ATTUCKS ST 0, WS, , 27105

File name (Image): FIRE-DAMAGED-INTERIOR.jpg



PIN: 6846-02-4917.000

Violation Type: Housing Violation

Block: 1382

Lot: 001

Location: 1511 ATTUCKS ST 0, WS, , 27105

File name (Image): FRONT-PORCH-CEILING.jpg



PIN: 6846-02-4917.000

Violation Type: Housing Violation

Block: 1382

Lot: 001

Location: 1511 ATTUCKS ST 0, WS, , 27105

File name (Image): MISSI7NG-WINDOWS.jpg



PIN: 6846-02-4917.000

Violation Type: Housing Violation

Block: 1382

Lot: 001

Location: 1511 ATTUCKS ST 0, WS, , 27105

File name (Image): DAMAGED-ROOF.jpg



PIN: 6846-02-4917.000

Violation Type: Housing Violation

Block: 1382

Lot: 001

Location: 1511 ATTUCKS ST 0, WS, , 27105

File name (Image): FRONT-EXTERIOR.jpg

