<u>C</u> (	ODE ENFORCEMENT PURSUANT TO HOUSING CODE:  SEC. 10-203(f)(1)
	SEC. 10-203(f)(2)
<u>C</u>	ASE SUMMARY:
PI W PI	OUSING FILE NO.: 2015040312 ROPERTY ADDRESS: 532 W ACADIA AV ARD: SOUTH ROPERTY OWNER(s): WILMA O. MOORE IS PENDENS #: 15m1258 DATE LIS PENDENS FILED: 9/3/2015
<u>D</u> I	UE PROCESS:
1.	The current <u>Complaint and Notice of Hearing</u> was issued <u>5/13/2015</u> and service was obtained by $\underline{\checkmark}$ certified mail; $\underline{\checkmark}$ regular; $\underline{\checkmark}$ posting; hand delivery and publication on <u>5/23/2015</u> . The Hearing was held on <u>6/12/2015</u> and the owner/agent did $\underline{\checkmark}$ did not appear and/or contact the Community Development Department regarding the complaint.
2.	The <u>Finding and Order</u> was issued on <u>8/20/2015</u> and service was obtained by <u>✓</u> certified; <u>✓</u> regular; <u>✓</u> posting; <u>—</u> hand delivery, and <u>—</u> publication on <u>8/30/2015</u> . The Order directed the owner to <u>vacate and close or repair</u> the dwelling within <u>30</u> days from receipt. The time for compliance expired on <u>9/30/2015</u> . The dwelling was found vacated and closed on <u>11/20/2015</u> .
3.	The dwelling became eligible for demolition under the <u>√</u> six (6) month rule 65% rule on <u>5/20/2016</u> .
4.	The notification letter was sent on <u>5/30/2018</u> advising the owner that the <u>Community Development/Housing/General Government Committee</u> of the City Council would be considering demolition of this dwelling at their meeting on <u>6/12/2018</u> . The notice further advised that if the owner(s) intended to request an extension of time, they should present evidence of their intent to the Community Development Director prior to the Committee meeting. The Director <u>was</u> was not contacted.
<u>C</u>	OMMENTS (if any):
<u>C(</u>	OUNCIL CONSIDERATION:
Tł	ne estimated cost to make repairs to needed to render this dwelling fit for human habitation:
	exceeds sixty-five percent (65%) of the value of the dwelling. is less than fifty percent (<50%) of the present value of the dwelling. is more than fifty percent (>50%) of the present value of the dwelling.
Es	stimated cost to repair structure \$12,787 Fair market value of structure \$32,500
	ased on the above information it is recommended that an Ordinance be adopted to cause this dwelling be:
	removed or demolished.  repaired or demolished and removed within ninety (90) days or, if eligible, repaired under In Rem provisions of the Minimum Housing Code with City Council approval. demolished and removed within ninety (90) days.