

# Community Development Housing General Government Committee

## **Demolition Review**

January 14, 2020

# -50 % Category

- DEFINITION cost of repairs are 50% below the structures Fair Market Value
- Properties vacant 6 months or more

#### C-3 Richard M. Miller 2419 Sink Street Case 2016101262 (Southeast Ward)

- Committee voted in December 2019 to have the owner make repairs and requested that repairs are in compliance by today's meeting.
- During our site visit 1/13/20 the property remains out of compliance

#### C-3 Richard M. Miller 2419 Sink Street Case 2016101262 (Southeast Ward)

- Due Process notifications of the property violations were sent to the owner as required by Ordinance.
- Minimum housing violations (12) As of 1/13/2020, 7 violations have been complied, 5 are remaining
- Lis pendens violations were submitted to the County Clerk's office & were filed 5/11/2017
- Hearing 12/30/2016 Repair & Vacate Order expired 5/25/2017
- Eligible for CDHGGC consideration— 12/25/2017
- Estimated cost to repair the structure \$3,273
- Fair Market value of Structure \$12,500

**C-3** 

#### 2419 Sink Street







**C-3** 

#### 2419 Sink Street

All pictures from 1/13/2020









# +50 % Category

- DEFINITION cost of repairs are more than 50% above the estimated value of the property
- Properties vacant over 6 months

#### C-4 Richard Settle & Toni Settle 1103 E. Sprague Street Case 2018120460 (Southeast Ward)

- Committee voted in October 2019 to have the owner make repairs and requested that repairs are in compliance by today's meeting.
- During our site visit on 1/13/2020 the property was in compliance.

#### C-4 Richard Settle & Toni Settle 1103 E. Sprague Street Case 2018120460 (Southeast Ward)

- Due Process notifications of the property violations were sent to the owner as required by Ordinance.
- Minimum housing violations (35) As of 1/13/2020 the property is in compliance
- Lis pendens violations were submitted to the County Clerk's office & were filed 2/15/2019
- Hearing 1/30/2019 Repair & Vacate Order expired 2/14/2019
- Eligible for CDHGGC consideration— 9/14/2019
- Estimated cost to repair the structure \$22,415
- Fair Market value of Structure \$10,000

C-4

### 1103 E. Sprague St.









**C-4** 

#### 1103 E. Sprague St

Picture from 1/13/2020

