

Community Development Housing General Government Committee

Demolition Review February 11, 2020

-50 % Category

- DEFINITION cost of repairs are 50% below the structures Fair Market Value
- Properties vacant 6 months or more

C-5 Richard M. Miller 2419 Sink Street Case 2016101262 (Southeast Ward)

- Due Process notifications of the property violations were sent to the owner as required by Ordinance.
- Minimum housing violations (originally12) As of 2/7/2020, 9 violations have been complied, 3 are remaining 1.Replace or repair defective siding, 2. weatherstriping around doors 3. replace loose wall or ceiling material. The customer placed a "No Trespassing" sign and the interior violations can not be verified.
- Lis pendens violations were submitted to the County Clerk's office & were filed 5/11/2017
- Hearing 12/30/2016 Repair & Vacate Order expired 5/25/2017
- Eligible for CDHGGC consideration- 12/25/2017
- Estimated cost to repair the structure \$3,273
- Fair Market value of Structure \$12,500

C-5 2419 Sink Street







C-5 2419 Sink Street

All pictures from 1/13/2020



C-5 2419 Sink Street All pictures from 2/7/2020

- Defective siding was painted over. (exterior)
- Weatherstriping around doors and
- loose wall/ ceiling material are inside the property.
- A **No Trespassing** sign prevents entry unless the property owner allows it or staff obtains an administrative warrant.









+50 % Category

- DEFINITION cost of repairs are more than 50% above the estimated value of the property
- Properties vacant over 6 months

C-6 Daryl R. Hinshaw & Wendy G. Hinshaw 4034 S. Main Street Case 2017050958 (Southeast Ward)

- Due Process notifications of the property violations were sent to the owner as required by Ordinance.
- Minimum housing violations (12)
- Lis pendens violations were submitted to the County Clerk's office & were filed 6/21/2018
- Hearing 4/27/2018 Repair & Vacate Order expired 6/17/2018
- Eligible for CDHGGC consideration- 2/6/2019
- Estimated cost to repair the structure \$9,016
- Fair Market value of Structure \$18,000

C-6 4034 S. Main Street



10/17/2018





C-6 4034 S. Main Street







+65% Category

DEFINITION: cost to repair properties exceed 65% of the fair market value. Properties in this category can be demolished 30 days after Council approval.

C-7 Daniel B. Souther, Heirs Geneva C. Pardue, Heirs 2450 Boone Avenue Case 2019030044 (Southwest Ward)

- Due Process notifications of the property violations were sent to the owner as required by Ordinance
- Minimum housing violations (23)
- Lis pendens all violations submitted to the County Clerk's office & were filed 12/3/2019
- Hearing 10/21/2019 Repair or Demolish Order expired 12/29/2019
- Eligible for CDHGGC consideration- 2/6/2020
- Estimated cost to repair the structure \$40,538
- Fair Market value of Structure \$15,300

C-7 2450 Boone Avenue





C-8 J H Lawson Jr., Heirs T S Lawson, Heirs 4561 Oak Ridge Drive Case 2019050795 (Northeast Ward)

- Due Process notifications of the property violations were sent to the owner as required by Ordinance
- Minimum housing violations (23)
- Lis pendens all violations submitted to the County Clerk's office & were filed 11/26/2019
- Hearing 11/7/2019 Repair or Demolish Order expired 1/12/2020
- Eligible for CDHGGC consideration- 1/12/2020
- Estimated cost to repair the structure \$38,932
- Fair Market value of Structure \$3,000

C-8 4561 Oak Ridge Drive







